Waste Site Reclassification Form

Date Submitted: 3/9/2000	Operable Unit(s):	200-SW-1	Control Number: 2000-010
Originator: Jim Golden	Waste Site ID:	200-E PAP	
Phone: 376-6961	Type of Reclassific Rejected: No Action: Interim Closed Closed Out:	○ ⊙	
This form documents agreement among the parties listed below authorizing classification of the subject unit as rejected, closed-out, or no action and authorizing backfill of the site, if appropriate. Final removal from the NPL of no action or closed-out sites will occur at a future date.			
Description of current waste site condition:			
The ash pit is a large open depression located east of the 284-E Powerhouse. It is divided into two parts by an earthen dam. The pit currently contains only a small amount ash.			
			ECEUVED) FEB 0 9 2005
Basis for reclassification: A waste determination of the Hanford Site 200 Area steam plant ash was performed in the early 1990s. The waste stream was determined to be nondangerous. Samples were analyzed using the TCLP (Toxicity Characteristic Leaching Procedure), and all were below the regulatory			
limits. The pH of the samples ranged from 7	.66 to 11.91, with an ave	rage of 9.27. It is recommended t	his site be reclassified to No Action.
Sheve Burnen DOE Project Manager Ecology Project Manager A EPA Project Manager	Signatu	ohn B. Price	